

13/7/21 SPECILAISED WORK - requires a contractor with relevant skills and knowledge of working in oak timber framing. Will require Listed Building Consent. Within Conservation area. - liaison required with Conservation Officer, and permission of the Diocese of Exeter. Remove moss from roof tiles and hip tiles and replace where these are damaged or missing, areas of significant decay removed and replaced, historic shake cracks within timbers professionally sealed. Gates repaired and rehung with replacement hinges or adaption

Contractor	date emailed	Response	quote considered at meeting
Carpenter Oak	27.10.22	Thank you for your consideration however we're unfortunately not in a position to undertake any conservation work owing to workload on new-build projects	
The Greenoak Framing Company	27.10.22	No Response	
ss Roofing Specialist	27.10.22	No Response	
Tamar Joinery Company	27.10.22	No Response	
Exeter Roofing	27.10.22	Verbal report - don't agree with survey and recommend leave the roof alone	
4 design Specialist Joinery	27.10.22	No Response	
Roof Smart	27.10.22	No Response	
AP Bourne Carpentry	27.10.22	We are based in Ashford Kent so don't travel this far for work	
Whitegates Joinery	27.10.22	No Response	
Heritage Roofing SW	5.1.23	Quotation received to be considered 7/2/23	16/2/23 approved subject to funding
Character Builders	9.1.23	Quotation received 1/2/23	
Bramhill Builders	9.1.23		
ss Roofing Specialist	5.1.23	No Response	
Davies Roofing	5.1.23	No Response	